

# Content

|                                    |          |                                     |           |
|------------------------------------|----------|-------------------------------------|-----------|
| <b>Machine Components</b>          | <b>9</b> | <b>Actuators</b>                    | <b>44</b> |
| Pins                               | 9        | <b>Valves</b>                       | <b>48</b> |
| Bolts, Screws, Nuts, and Washers   | 9        | <b>Ores</b>                         | <b>49</b> |
| Other Types of Bolts and Screws    | 11       | <b>Fuel</b>                         | <b>49</b> |
| Screws                             | 12       | Gas and Gasoline Manufacture        | 52        |
| Screw Drives                       | 13       | Gas                                 | 52        |
| Nuts and Washers                   | 14       | Gasoline                            | 53        |
| Rivets                             | 15       | Drilling Rig                        | 54        |
| Drill & Fit Workshop               | 15       | Coke                                | 55        |
| Threads                            | 16       | Furnaces and Steel                  | 56        |
| Thread Standards                   | 16       | Furnaces                            | 56        |
| Thread Angle                       | 17       | Bloomery                            | 57        |
| Power Screws or                    |          | Blast Furnace                       | 57        |
| Trapezoidal Threads                | 18       | Double Bell System                  | 59        |
| Pipe Thread                        | 20       | Bell-less System                    | 59        |
| Buttress Thread                    | 20       | Ingots and Slaps                    | 61        |
| Guide-ways                         | 21       | Continuous-Casting Processes        | 61        |
| Gears                              | 24       | Bessemer Process                    | 64        |
| Geometry and Nomenclature          | 24       | Electric Furnaces                   | 65        |
| Special Gears                      | 26       | Electric Arc Furnace                | 65        |
| Ordinary Gear Trains               | 26       | Bar Stock                           | 65        |
| Compound Gear Train                | 26       | Heat Treatment                      | 66        |
| Epicyclical Gear Trains            | 26       | <b>Iron and Steel</b>               | <b>67</b> |
| Gear Box                           | 27       | Carbon Steel                        | 67        |
| Special Mechanisms                 | 27       | Low Carbon Steel                    | 68        |
| Springs                            | 29       | Higher Carbon Steel                 | 68        |
| Spring Materials                   | 29       | Medium Carbon Steel                 | 68        |
| Helical Extension and              |          | High Carbon Steel                   | 68        |
| Compression Springs                | 29       | Eutectic System                     | 70        |
| Shear Stress                       | 30       | Iron-carbon phase diagram           | 70        |
| Curvature Effect                   | 30       | Alloy Steel                         | 72        |
| Torsion Springs                    | 30       | Tool Steel                          | 73        |
| Torsion Bar Springs                | 31       | Water-hardening grades              | 73        |
| Flat or Leaf Springs               | 31       | Air-hardening grades                | 73        |
| Multileaf Springs                  | 31       | Cold-working grades                 | 73        |
| Bellville Springs                  | 32       | Steel Shapes                        | 74        |
| Load-Deflection Diagram            | 32       | Cast Iron                           | 75        |
| Bearings                           | 34       | Production                          | 75        |
| Plain Bearings or Journal Bearings | 34       | Varieties of cast iron              | 75        |
| Rolling Bearings                   | 34       | Malleable Iron                      | 76        |
| Rolling Elements                   | 35       | Other Ferrous Materials             | 76        |
| Directions of Principal Forces     | 35       | <b>Nonferrous Metals and Alloys</b> | <b>77</b> |
| Number of Rolling Bearing Rows     | 37       | Nonferrous Metals                   | 77        |
| Reliability Requirement            | 38       | Nonferrous Alloys                   | 78        |
| Shock Force                        | 38       | <b>Galvanic Action</b>              | <b>79</b> |
| Pillow Block Bearing               | 38       | Galvanic Series                     | 79        |
| Feather Key Joints                 | 40       | <b>Casting</b>                      | <b>80</b> |
| Splined Shafts and Fittings        | 41       | Expendable mold casting             | 80        |
| Detachable Unions                  | 41       | Sand Casting                        | 80        |
| Seals, Gaskets, Glands,            |          | Plaster casting                     | 80        |
| and Bellows                        | 42       | Shell molding                       | 81        |
| Belts and Chains                   | 43       | Investment Casting                  | 81        |

|                                    |           |                                     |            |
|------------------------------------|-----------|-------------------------------------|------------|
| Permanent casting                  | 81        | and Nugget                          | 100        |
| Die Casting                        | 81        | Electrode Hold Time                 | 101        |
| Centrifugal casting                | 81        | Welding with 3 -Phase AC            | 101        |
| Continuous Casting                 | 82        | Welding with Media                  |            |
| A Foundry Facility for             |           | Frequency Inverters                 | 102        |
| Your Small Workshop                | 83        | <b>Soldering and Brazing</b>        | <b>103</b> |
| Safety First                       | 83        | General                             | 103        |
| All the Bits and Pieces            | 83        | Filler Metals                       | 103        |
| Cubicle                            | 83        | Flux104                             |            |
| Melting Bronze or Cast Iron        | 84        | Silver Soldering                    | 104        |
| Cover                              | 85        | Pipe Soldering/Brazing              | 105        |
| Fuel                               | 85        | Tools                               | 105        |
| Firing the Lining                  | 86        | Soldering Iron                      | 106        |
| Contraction on cooling             | 86        | <b>Tools</b>                        | <b>107</b> |
| Foundry Sand                       | 86        | Vise (AE), Vice (BE)                | 107        |
| Blower                             | 86        | Anvil and Hammer                    | 107        |
| <b>Forging</b>                     | <b>87</b> | Pliers, Nippers, Cutters, Strippers | 107        |
| Advantages                         | 87        | Screwdrivers                        | 108        |
| A Forge                            | 87        | Wrenches (AE), Spanners (BE)        | 110        |
| Open-Die Forging                   | 87        | Hand Files                          | 113        |
| Press Forging,                     |           | Classification                      | 113        |
| Drop Hammer Forging                | 87        | Taps and Dies                       | 114        |
| Upset Forging                      | 88        | Taps                                | 114        |
| Automatic Hot Forging              | 88        | Screwing Dies                       | 115        |
| Roll Forging                       | 88        | Lubrication of Taps and Dies        | 116        |
| Net-Shape Forging                  | 88        | Tap and Die-Sharpening              | 116        |
| <b>Welding</b>                     | <b>89</b> | Saws                                | 117        |
| Welding by the                     |           | Hacksaw                             | 118        |
| Oxy-Acetylene Process              | 89        | <b>Power Hacksaw</b>                | <b>119</b> |
| Fuel Gas                           | 89        | <b>Grinders</b>                     | <b>120</b> |
| Notes of Safety                    | 90        | Breaking Up a Grinding Wheel        | 120        |
| Blowpipe or Torch                  | 91        | Dressing a Grinding Wheel           | 120        |
| Regulators                         | 91        | Abrasion                            | 121        |
| Canvas-Rubber Hose                 | 91        | Grinding Wheels                     | 121        |
| Filler Wire                        | 92        | Vitrified bond                      | 121        |
| Fusion Welding                     | 92        | <b>Drilling Machines</b>            | <b>122</b> |
| Butt Weld                          | 92        | <b>Drills</b>                       | <b>125</b> |
| Arc Welding                        | 93        | Terms used to describe a drill      | 125        |
| General                            | 93        | Choice of Angles                    | 126        |
| Notes of Safety                    | 93        | Helix Angle                         | 127        |
| Electrodes                         | 94        | Combination Center Drill            | 128        |
| Screens                            | 94        | Spade-Bit Drill                     | 128        |
| Practice Welding Beads             | 94        | Core Drill                          | 129        |
| T.I.G and M.I.G Welding            | 95        | Cone-Cut Drill                      | 129        |
| Function                           | 95        | Countersink                         | 129        |
| Engineering Weld Symbols           | 96        | Reamers                             | 129        |
| Weld Symbols for Types of Joints   | 96        | Drill Sharpening                    | 130        |
| Resistance Welding                 | 98        | Drill Grinding Jig                  | 130        |
| Fundamentals                       | 98        | Sheet Cutting and Sheet Bending     | 131        |
| Projection, Seam, and Butt Welding | 98        | Sheet Cutting                       | 131        |
| Resistance Spot Welding            | 99        | Press Brakes                        | 132        |
| Stationary Resistance              |           | <b>Shapers</b>                      | <b>133</b> |
| Spot Welding Machine               | 99        | Types                               | 133        |
| Welding Lines                      | 100       | Operation                           | 133        |
| Welding Current, Welding Time      |           | Applications                        | 133        |

|                                    |            |                                  |            |
|------------------------------------|------------|----------------------------------|------------|
| <b>Broching</b>                    | <b>134</b> | Clamping Workpieces to the Table | 158        |
| <b>Lathes</b>                      | <b>135</b> | Clamping a Workpiece             |            |
| Construction                       | 135        | to an Angle Plate                | 159        |
| Headstock                          | 135        | Clamping Workpieces in Fixtures  | 159        |
| Bed                                | 136        | Holding Workpieces               |            |
| Feedscrew                          | 136        | between Centers                  | 159        |
| Metric and Imperial Threads        | 136        | Holding Workpieces in the Vise   | 160        |
| Carriage                           | 137        | Placing Workpieces in the Vise   | 160        |
| Turning, Facing, and Boring        | 137        | Indexing                         | 161        |
| Cross-Slide                        | 138        | Edge Finder                      | 161        |
| Compound Rest                      | 138        | Cutting Oils                     | 161        |
| Toolpost                           | 138        | Method of Use                    | 161        |
| Tailstock                          | 138        | Plain Milling                    | 162        |
| Types of Metal Lathes              | 139        | Mounting the Workpiece           | 162        |
| NC Lathe, CNC Turning Center       | 141        | Selecting the Cutter             | 162        |
| Cutting Tools                      | 142        | Setup                            | 162        |
| Lathe Dog                          | 143        | Gang Milling                     | 163        |
| Positions                          | 143        | Milling the Keyway of            |            |
| <b>Milling Machines</b>            | <b>144</b> | a Woodruff Key                   | 163        |
| General                            | 144        | Milling Keyway for               |            |
| Basic Function                     | 144        | Round-End Machine Key            | 163        |
| Basic Construction                 | 144        | Sawing and Parting               | 163        |
| Types of Milling Machines          | 145        | Splined Shafts and Fittings      | 163        |
| Construction of Conventional       |            | <b>Honing and Lapping</b>        | <b>164</b> |
| Milling Machines                   | 145        | <b>Dust, Dust Fires,</b>         |            |
| CNC – Milling Machines             | 146        | <b>and Dust Explosions</b>       | <b>165</b> |
| Safety Rules                       | 148        | Hazards due to Combustible Dusts | 165        |
| Tools and Equipment                | 149        | Causes of Dust Fire              |            |
| Cutters                            | 149        | and Dust Explosions              | 166        |
| Milling Cutter Nomenclature        | 149        | Hood Types                       | 167        |
| Types of Cutters                   | 150        | Hood Design Factors              | 167        |
| Plain or Helical Cutters           | 150        | Hood Nomenclature                | 168        |
| Rotation                           | 150        | Direction of Air Flow            | 170        |
| Helical Milling Cutters            | 150        | Air Cleaning Devices             |            |
| Metal Slitting Saw Milling Cutters | 150        | and Dust Collectors              | 170        |
| Side Milling Cutters               | 150        | Fabric Collectors                | 172        |
| End Milling Cutters                | 151        | Electrostatic Precipitator       | 173        |
| T-Slot Milling Cutters             | 151        | Fans                             | 175        |
| Key Slot Milling Cutters           | 152        | Ejector Fans                     | 175        |
| Form Milling Cutters               | 152        | Axial Fans                       | 175        |
| Fly Cutters                        | 152        | Propeller Fans                   | 175        |
| Gear Hobs                          | 153        | Tube-Axial Fans                  | 176        |
| Interchangeable Carbide Tips       | 154        | Vane-Axial Fans                  | 176        |
| Arbors                             | 154        | Centrifugal Fans                 | 177        |
| Standard Milling Machine Arbor     | 155        | Centrifugal Fan Components       | 177        |
| Up Cut Milling/Down Cut Milling    | 155        | Noise                            | 177        |
| Collets, Spindle Adapters,         |            | Safety and Accessories           | 178        |
| and Quick-Change Tooling           | 155        | Fire Extinguishing Systems       |            |
| Collets                            | 156        | and Measures                     | 179        |
| Spindle Adapters                   | 156        | Plant Fire Protection            | 180        |
| Quick-Change Tooling               | 156        | Fire Fighting Measures           | 181        |
| Milling Vises                      | 156        | Fire Extinguishing Agents        | 181        |
| Offset Boring Head                 | 157        | Explosion Prevention             | 181        |
| T-Slots                            | 157        | Welding and Cutting              | 182        |
| Methods of Mounting Workpieces     | 158        | Ignition Process                 | 182        |

|  |            |                                     |     |
|--|------------|-------------------------------------|-----|
| Protective Measures                    | 182        | Scope                               | 221 |
| Auto Ignition                          | 182        | General                             | 221 |
| Protective Measurements                | 183        | Minimising risks                    | 221 |
| Designed Explosion Protection          | 184        | Special target groups               | 221 |
| Explosion Pressure Resistant           |            | Relation between                    |     |
| Design for the                         |            | Instruction and Product             | 222 |
| Maximum Explosion Pressure             | 184        | Different Models of a Product       | 222 |
| Explosion Disengagement,               |            | Units of Measurement                | 222 |
| Explosion Interruption                 | 184        | Understandable text                 | 222 |
| Air lock                               | 184        | Contents of a Manual                | 223 |
| Rapid Action Valve                     | 185        | Chapter 1, Identification           | 224 |
| Suppression Barrier                    | 186        | Chapter 2, Specification            |     |
| Diverter                               | 186        | of the product                      | 225 |
| <b>Workshop Drawing</b>                | <b>190</b> | Identification of the Manual        | 226 |
| <b>Engineering Tolerance</b>           | <b>193</b> | Modifications of the Product        | 226 |
| General                                | 193        | Safety notes, General warnings      | 226 |
| Limit Deviations for                   |            | Environmental notes                 | 227 |
| Linear Dimensions                      | 194        | Technical Data                      | 228 |
| ISO Standards for                      | 195        | Conformity declaration              | 229 |
| Limits and Fits                        | 195        | Chapter 3, Preparing the            |     |
| Geometrical Dimensioning               |            | Product for Use                     | 230 |
| and Tolerancing (GD&T)                 | 198        | Assembly and                        |     |
| <b>Surface Texture and Scraping</b>    | <b>199</b> | Mounting Procedures                 | 231 |
| <b>Behavior of Material under Load</b> | <b>200</b> | Chapter 4, Operating Instructions   | 232 |
| Stress and Strain                      | 200        | Safe operating and function         | 232 |
| Strain-Stress Behaviour                | 201        | Signals to be observed              | 232 |
| Bending, Buckling, and Torsion         |            | Personal protection                 | 232 |
| of Beams and Shafts                    | 204        | Chapter 5, Maintenance              | 233 |
| <b>Electrical Installations</b>        | <b>206</b> | Maintenance                         | 233 |
| General                                | 206        | Instructions for repair             |     |
| Electrical Distribution                | 206        | and replacement parts               | 233 |
| Circuit Breaker                        | 207        | Instruction for fault-finding       | 234 |
| Ground Fault Interrupter               | 207        | Failure, Repair,                    |     |
| Branch Circuits                        | 208        | and Troubleshooting                 | 234 |
| Appliance, and Individual Circuits     | 208        | Chapter 6, Optional Modules         |     |
| Summary                                | 209        | and Special Tools                   | 235 |
| Load Requirements                      | 209        | Special Tools and Equipment         | 235 |
| Low-Voltage Circuits                   | 209        | Chapter 7, Maintenance Instructions |     |
| Separate Wiring Circuits               | 210        | for Unskilled Persons               | 236 |
| <b>A Mounting Instruction</b>          | <b>211</b> | Chapter 8, List of Spare Parts      | 239 |
| Bicycle Carrier                        | 211        | Chapter 9, Taking the Product       |     |
| General                                | 211        | out of Operation                    | 241 |
| Instructions for Assembling            |            | General                             | 241 |
| the Bicycle Carrier                    | 212        | Storage                             | 241 |
| Instructions                           | 213        | Recycling                           | 241 |
| Before mounting the bicycle            |            | Disposal                            | 241 |
| carrier onto your vehicle              | 214        | Table of contents                   | 241 |
| Sequence markers                       | 214        | Script Writing                      | 242 |
| Active Sentences                       | 214        | Standard Communication Principles   | 242 |
| How to fasten the bicycles on          |            |                                     |     |
| the mounted bicycle carrier            | 217        |                                     |     |
| <b>Specifications</b>                  | <b>219</b> |                                     |     |
| <b>How to make a Manual</b>            | <b>220</b> |                                     |     |
| Introduction                           | 220        |                                     |     |
| Preparation to make a Manual           | 221        |                                     |     |